Datasheet / Datenblatt


Article number / Artikelnummer: 4084FB

EAN number / EAN: 4250384743048
Freight category / Frachtkategorie: A

Ornamental bollard steel tube Ø 89 mm, removable, with triangular locking mechanismacc. with DIN 3223, self-engaging lockwith hot-dip galvanized ground socket part-no. 470.10

Stilpoller Serie 4084B Ø 89 mm, herausnehmbar, selbsteinrastende Verriegelung, mit feuerverzinkter Bodenhülse Typ 470.10, mit Dreikantverschluss nach DIN 3223





Item description

Ornamental bollard steel tube Ø 89 mm

Ornamental bollard
of steel tube Ø 89 mm
approx. 950 mm above ground, hot-dip galvanized and coated iron glimmer (DB 703)

- removable, with triangular locking mechanismacc. with DIN 3223, self-engaging lockwith hot-dip galvanized ground socket part-no. 470.10

Artikeltext

Stilpoller Serie 4084B Ø 89 mm

Stilpoller
aus Stahlrohr Ø 89 mm
ca. 950 mm Überflur, feuerverzinkt und Eisenglimmergrau (DB 703) beschichtet

- herausnehmbar, selbsteinrastende Verriegelung, mit feuerverzinkter Bodenhülse Typ 470.10, mit Dreikantverschluss nach DIN 3223

Technical specifications

Weight: 13,5 kg
Dimensions: 89 mm x 1300 mm x 89 mm
material:
S235 JR

surface:
hot dipped galvanized and powder coated

Technische Daten

Gewicht: 13,5 kg
Abmessungen: 89 mm x 1300 mm x 89 mm
Material:
S235 JR

Oberfläche:
Feuerverzinkt und Pulverbeschichtet

* All data are approximate values (partly with industry-standard rounding for better understanding) and serve only for product understanding, but not as a basis for the design of accessories, storage solutions, adaptations, combination products or the like. All information is without guarantee, for possible errors and resulting consequences we assume no responsibility.
* Alle Angaben sind Richtwerte (teilweise mit branchenüblichen Rundungen zum besseren Verständnis) und dienen leidglich zum Produktverständnis, nicht aber als Basis zum Bau von Zubehörteilen, Lagergestellen, Adaptierungen, Kombinationsprodukten oä. Alle Angaben sind ohne Gewähr, für evtl. Fehler und resultierende Folgen übernehmen wir keine Verantwortung.